1.0000 Each(s)

Comment: Qty.:

Pick:

Qty Part Number

1 D2572

1.0000 Each(s)/Unit

Total :

Description

Saddle Fwd Inside

FlylorSP

Da	rt	Ae	ros	pace	Ltd
----	----	----	-----	------	-----

W/O:			W	ORK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	\$								
								<b>*</b>	
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQA</b> :		Date:	
					QA: N	/C Closed:		_ Date: _	
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NCR	(1)			
DATE	CTED	Description of NC			ction B	Verifica	tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
		·							
Ti.				·					
							:		

Monday, 5/28/200/ 11:56:42 AM Date: , Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742011 Job Number: 32522 Job Number: Description: Seq. #: Machine Or Operation: Saddle, Aft, Out 6.0 D2573 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Comment: Qty.: Pick: 50 **Qty Part Number** Description Saddle Aft Outside 1 D2573 D2574 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: Description Qty Part Number Saddle Aft Outside\_ 1 D2574 8.0 D2876 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Pick: 54 Qty Part Number Description Saddle Spacer 2 D2876 D2877 9.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: Pick: **Qty Part Number** Description Saddle Spacer 2 D2877 D34031 10.0 16.0000 Each(s)/Unit Total: 16.0000 Each(s) Comment: Qtv.: Pick: Qty Part Number Description 16 D3403-1 Bushing Set Screw 11.0 D2747 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Comment: Qty.: Pick: 1/11/or 50 Description Qty Part Number 4 D2747


	rospace		1410	DK ODDED OUANOE					
<b>W</b> /O:			WC	RK ORDER CHANGE	S		<b>.</b>		1
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
		,							
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
					QA:	N/C Close	d:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	ICE (NC	R)			
DATE	OTED	Description of NC		Corrective Action Section		Verific	ation	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	QC Inspecto
			1 1	**	1	I		1	1
:									

Monday, 5/28/2007 11:56:42 AM Date: , Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Job Number: 32522 Part Number: D412742011 Job Number: Description: Seq. #: Machine Or Operation: D35331 Set Screw 12.0 2.0000 Each(s) 2.0000 Each(s)/Unit Total: Comment: Qty.: Set Screw BATCH: AN4C6A 13.0 Total: 16.0000 Each(s) Comment: Qty.: 16.0000 Each(s)/Unit Pick: **Qty Part Number** Description 16 AN4C6A Bolt D34033 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description Qty Part Number 8 D3403-3 Bushing 15.0 D3405041 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Pick: **Qty Part Number** Description 1 D3405-041 GHW Lug D3405043 16.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: Pick: SP Qty Part Number Description GHW Lug 1 D3405-043 17.0 AN4C46A Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Pick: Qty Part Number Description 7/11/02 SQ 4 AN4C46A

Dart Ae	rospace L	_td						
<b>W</b> /O:			WC	RK ORDER CHANGE	S			
DATE	STEP	. PR	OCEDURE CHAI	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _	
						I/C Closed:	Date: _	
NCR:			·	ER NON-CONFORMAN	ICE (NCF	₹)		
DATE	STEP	Description of NC	<u> </u>	Corrective Action Section		Verification	Approval	Approva
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		Chief Eng	QC Inspecto
					-			
				N.				

Monday, 5/28/2007 11:56:42 AM Date: Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKIDTUBE Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742011 Job Number: 32522 Job Number: Description: Seq. #: Machine Or Operation: BOLT AN4C52A 18.0 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: Pick: Qty Part Number Description M103911 8 AN4C52A AN6C12A 19.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description **Qty Part Number** Bolt 8 AN6C12A AN960C416L 20.0 Comment: Qty.: 32.0000 Each(s)/Unit Total: 32.0000 Each(s) Pick: 50 Qty Part Number Description Washer 100651; △ 32 AN960C416L AN960C616L WASHER 21.0 Comment: Qty.: 8.0000 Each(s)/Unit Total: 8.0000 Each(s) Pick: Description Qty Part Number Description Batch
Washer M/8822 8 AN960C616L Nut 22.0 MS210434 Comment: Qty.: 29.0000 Each(s)/Unit Total: 29.0000 Each(s) Pick: Qty Part Number Batch 29 MS21043-4Nut /4105 4/11/12 50

W/O:			WC	RK ORDER CHANGES	5			·
DATE	STEP	··· PR	OCEDURE CHAI		Ву	Date Q	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
		.·		·				
Part No	:	PAR #:	Fault Cate	jory:				-
NCR:	.		WORK ORDE	ER NON-CONFORMAN	· · · · · · · · ·		Date: _	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section E Action Description Chief Eng	Sign 8	Verification Section C	Approval Chief Eng	Approva QC Inspecto
	<del></del>				Date			
					Date			
					Date			
					Date			
					Date			



W/O:			WC	RK ORDER CHANGES	3			***	
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
			•						
						_ (			
Part No	);	PAR #:	Fault Cate	gory:	NCR: Yes	(No) DC	A: _	Date: _	Muld
					QA:	N/C Close	ed:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NC	R)			
DATE	T								
	STED	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approva
DATE	STEP	<b>Description of NC</b> Section A	Initial Chief Eng	Corrective Action Section   Action Description Chief Eng	Sign Date	& Sec	cation tion C	Approval Chief Eng	Approva QC Inspect
DATE	STEP	<b>Description of NC</b> Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspecto
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sec		Approval Chief Eng	Approva QC Inspect

	day, 5/28/2007 11:56:43 AM	
User: Kim	Johnston	Process Sheet
• Customer:	CU-DAR001 Dart Helicopters Services	Drawing Name: FLOAT SKIDTUBE
Job Number:	32522	Part Number: D412742011
Job Number:		
Seq. #:	Machine Or Operation:	Description :
28.0	D34561	washer 
Commo	ent: Qty.: 1.0000 Each(s)/Unit Total :	: 1.0000 Each(s)
O SOME	Pick:	. 1.0000 2401(0)
	Qty Part Number Description	133926 SP
	1 D3456-1 WASHER	June
29.0	AN4C7A	Bolt \\
Comme	ent: Qty.: 4.0000 Each(s)/Unit Total:	: 4.0000 Each(s)
	Bolt	4//0
	Batch: 110/427 V	7/11/62 5/ (X)
30.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
Comme	ent: INSPECT 100% KITS FOR COMPLET	TENESS 2 4 (17)
31.0	PACKAGING 1	PACKAGING RESOURCE #1
Comme	ent: PACKAGING RESOURCE #1  Identify and pack for shipping as per Pl	PPP D442-742-011 /
	Location:	(=7/11/07 (1)
32.0	QC21	FINAL INSPECTION/WO RELEASE
Comme		L) 28/11/07
Commis	FINAL INSPECTION/W/O RELEASE	
Job Completion		
		W St-11-07
		1/2 01 (1 91
	•	
		·

<b>Dart</b>	Aer	osp	ace	Ltd

W/O:			WC	ORK ORDER CHAN	GES		<del></del>	
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date (	Appro Chief Er Prod M	Approval ag / gr QC Inspector
		,						
				•				
				•				
		·						
Part No	•	PAR #:	Fault Cate	gory:				
							Date	9: <u>.</u>
NCR:		•	WORK ORD	ER NON-CONFORM	MANCE (NCF	₹)		
DATE	STEP	Description of NC			ection B	Verificati	ion Appro	val Approval
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		C Chief E	ng QC Inspector
								•
							-	
					:			
<del> </del>								
			·					

Dart Aerospace Ltd. Monday, 5/28/2007 11:57:11 AM Date Kim Johnston User **Process Sheet** : FLOAT SKID ASSEMBLY **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number : 32522A : 12876 Estimate Number : D412742041 Part Number P.O. Number S.O. No. : MX D3391 REV F **Drawing Number** This Issue : N/A Project Number Prsht Rev. : LANDING GEAR **Drawing Revision** First Issue Material Previous Run 6/30/2007 Qty: 1 Um: Due Date Written By Checked & Approved By KJ/JLM Comment ECN 773 dwg @ rev.D EC Est Rev B 06.02.13 JLM Est Rev:C 07-05-28 As per Rev F **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: DOCUMENT CONTROL 1.0 DC Comment: DOCUMENT CONTROL Ma If D412-742-041 is a W/O on it's own, Photocopy bluefile and create labels per PPP D412-742-041 D3391013 Mid Tube Assembly 2.0 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: pick: Qty Part Number Description Batch D3391-013 Mid Tube Assembly 3.0 D3391015 Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) pick: Part Number Description D3391-015 Aft Tube Assembly

WEARSHOE

1.0000 Each(s)

M. f. / BK 07/11/07

D35641

WEARSHOE Batch:

1.0000 Each(s)/Unit

Total:

Comment: Qty.:

4.0

Each

Dart Ae	rospace	e Ltd							
W/O:			WC	RK ORDER CHANGES	3				
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cateç	Jory:	NCR: Yes	No <b>DQ</b>	A:	Date:	
					QA: N	C Close	d:	_ Date:	·····
NCR:		V	WORK ORDE	ER NON-CONFORMAN	CE (NCR	)			
		Description of NC	<u> </u>	Corrective Action Section		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
		•							-
		,							

Monday, 5/28/2007 11:57:11 AM Date: Kim Johnston User: **Process Sheet** Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Job Number: 32522A Part Number: D412742041 Job Number: Description: Seq. #: Machine Or Operation: WEARSHOE 5.0 D35643 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: **WEARSHOÆ** Batch: WEARSHOE 6.0 D35645 Comment: Qty.: 1.0000 Each(s) 1.0000 Each(s)/Unit Total: WEARSHOE Batch: GASKET 7.0 D35661 Comment: Qty.: 2.0000 Each(s) 2.0000 Each(s)/Unit Total: **GASKET** Batch: GASKET 8.0 D35665 1.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: GASKE Batch: BOLT 9.0 AN3C4A Comment: Qty.: 24.0000 Each(s)/Unit Total: 24.0000 Each(s) **BOLT** Batch: BOLT 10.0 AN3C6A Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) **BOLT** Batch: **BOLT** 11.0 AN3C7A Comment: Qty.: 8.0000 Each(s) 8.0000 Each(s)/Unit Total:

BOLT Batch:

Dart Ae	rospace	<b>Ltd</b>								
W/O:			WC	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			-				_			
Part No	:	PAR #:	Fault Cate	gory:	NCF	R: Yes	No DQ	<b>A</b> :	Date:	
						QA: N	I/C Close	d:	Date: _	
NCR:		\	WORK ORD	ER NON-CONFORM	IANCE	(NCF	₹)			
		Description of NC		Corrective Action Sec	ction B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign 8	Secti		Chief Eng	QC Inspector
								!		
		*								

		Description of NC		Corrective Action Section E	3	Verification	A = = = = = = = = = = = = = = = = = = =	Ammunical
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspecto
		,						
				•				

Customer: CU-DAR001 Dart Helicopters Services  Drawing Name: FLOAT SKID ASSEMBLY  Part Number: D412742041  Job Number:  Seq. #: Machine Or Operation: Description:  12.0 AN960C10L washer  Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s)  washer  Batch: 10.5 143  13.0 MS27039C412 SCREW  Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)	
Seq. #:   Machine Or Operation:   Description :	
Seq. #:   Machine Or Operation:   Description :	
12.0 AN960C10L washer  Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s)  washer Batch: 10.105/43  13.0 Ms27039C412 SCREW  Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)	
Comment: Qty.: 44.0000 Each(s)/Unit Total: 44.0000 Each(s)  washer Batch:	
Washer Batch: 10 105 143  13.0 MS27039C412 SCREW  Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)	
Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)	1
SCREW Batch: M 12726 MI-1/ BK	)
14.0 NAS1515H4L Inventory	
Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)  Inventory,  Batch: 105408	
15.0 AN960C416L WASHER	
Comment: Qty.: 4.0000 Each(s)/Unit Total : 4.0000 Each(s)  WASHER  Batch: 105793	R
16.0 HAND FINISHING1 HAND FINISHING RESOURCE #1	$\overline{IX}$
Comment: HAND FINISHING RESOURCE #1	
1-Spray inside tube of D3391-021/-023/-025 with LPS-3 as per Dwg D3391  A/R LPS-3	
2-Install tubes together and seal them all the way around using Sikaflex 241/291. Ensure tube ends line-up with saddle holes for proper alignment, using 7/16" "T" Pins.  A/R Sikaflex-241/-291  Expiry date:	
3-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Coat bolts with LPS "procyon".  Seal all bolts with sikaflex exept ones with inserts on inside of tube ,hand tighten only bolts with no sikaflex.  A/R LPS Procyon	7/11/0
A/R Sikaflex-241/-291 — 105585 Expiry date: 08/07	
4-Remove "T" pins once sikaflex is dry.	00000

W/O:			WO	RK ORDER CHANGES	3						
DATE	STEP					Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto			
Part No	:	PAR #:	PAR #: Fault Category: N				NCR: Yes No DQA: Date: Office Date: Date:				
NCR:			WORK ORDE	R NON-CONFORMAN	•		Date				
DATE	OTED	Description of NC		В	Verification	Approval	I Approva				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspecto			

Monday, 5/28/2007 11:57:11 AM Date: Kim Johnston **Process Sheet** User: Drawing Name: FLOAT SKID ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412742041 Job Number: 32522A Job Number: Description: Seq. #: Machine Or Operation: 5-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser. INSPECT WORK TO CURRENT STEP QC5 17.0 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 18.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-742-041 PPP Rev: FINAL INSPECTION/W/O RELEASE 19.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion u H.11.07

Dart Aerospace	e Ltd
----------------	-------

		<del> </del>						
W/O:			W	ORK ORDER CHANG	ES		<del></del>	
DATE	STEP	PROCEDURE CHANGE				Date C	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<del></del>								
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA:_	Date: _	
					QA: N	C Closed: _	Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NCR	)		
DATE	STEP	Description of NC Section A		ion B	Verification Approval		Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
					:			

